# SHOCKTEST VIEW

Software for measuring shocks with sensors on 3 axes
(The ideal complement to the Shocktest art. VOH 31.00061)

The Software has two modes :

- One mode for the shocks acquisition
  - Acquisition and record of shocks
  - Possibility to enter proper datas to the file :
    - operator, height of shocks, axis of shocks

- One mode for processing and reading the measurements files
  - Simple and vanguard tool for reading files :
    - Shocks zooming
    - Shocks detection
    - Selection of the displayed axes
    - Printing, exporting and datas back-up